

**STUDY REPORT RR-02
WHITEWATER BOATING TAKE-OUT
IMPROVEMENT FEASIBILITY**

ATTACHMENT A

PHOTOGRAPHS OF THE WARD'S FERRY BRIDGE TAKE-OUT SITE

List of Photos

Photo No.	Description	Page No.
Photo 1.	Ward’s Ferry Bridge Take-Out Site, Looking Upstream from Existing Bridge. Note Old Bridge Abutments and User-Defined Access Trail. (Water Elevation 759 ft msl at Don Pedro Dam.).....	1
Photo 2.	Ward’s Ferry Bridge Take-Out Site, Vault Toilet on River Left at South End of the Existing Bridge.....	1
Photo 3.	Ward’s Ferry Bridge Take-Out Site River Left and River Right Under High Water Elevation Conditions. (Water Elevation 827 ft msl at Don Pedro Dam.)	2
Photo 4.	Ward’s Ferry Bridge Take-Out Site Depicting Steep Banks, River Left and River Right.....	2
Photo 5.	Ward’s Ferry Bridge Take-Out Site, Showing Height from River to Bridge Deck and Outfitter Hoisting Rafts from River to Bridge Deck.	3



Photo 1. Ward's Ferry Bridge Take-Out Site, Looking Upstream from Existing Bridge. Note Old Bridge Abutments and User-Defined Access Trail. (Water Elevation 759 ft msl at Don Pedro Dam.)



Photo 2. Ward's Ferry Bridge Take-Out Site, Vault Toilet on River Left at South End of the Existing Bridge.



Photo 3. Ward's Ferry Bridge Take-Out Site River Left and River Right Under High Water Elevation Conditions. (Water Elevation 827 ft msl at Don Pedro Dam.)



Photo 4. Ward's Ferry Bridge Take-Out Site Depicting Steep Banks, River Left and River Right.



Photo 5. Ward's Ferry Bridge Take-Out Site, Showing Height from River to Bridge Deck and Outfitter Hoisting Rafts from River to Bridge Deck.