

**STUDY REPORT TR-03
WETLAND HABITATS**

ATTACHMENT B

REPRESENTATIVE PHOTOGRAPHS

List of Photos

Photo No.	Description	Page No.
Photo 1.	Sixbit Gulch Large bedrock and boulder outcrops occurred along the perimeter of the wetland in this moderately confined drainage.....	1
Photo 2.	Sixbit Gulch Hummocks of naked sedge (<i>Carex nudata</i>) intermixed with Sonoma hedgenettle (<i>Stachys stricta</i>), springseep monkeyflower (<i>Mimulus guttatus</i>), and an occasional red willow (<i>Salix laevigata</i>).	1
Photo 3.	Sixbit Gulch A paved road crossed the channel near transect SG-06, which appears to be unused due to dense vegetation coverage. The road provides an opening in the dense riparian shrubs for sedge, springseep monkey flower (<i>Mimulus guttatus</i>) and Sonoma hedgenettle (<i>Stachys stricta</i>) to flourish.....	2
Photo 4.	Poorman's Gulch Shallow soils overlay bedrock substrates, with hummocks of naked sedge and mixed herbs.	2
Photo 5.	Poorman's Gulch Exposed bedrock supports perennial ryegrass (<i>Lolium perenne</i>), and annual beardgrass (<i>Polypogon monspeliensis</i>) at the perimeter.	3
Photo 6.	Poorman's Gulch Patches of red willow and spice bush (<i>Calycanthus occidentalis</i>) alternated with naked sedge hummocks and open bedrock, which occurred more frequently around pools located at the upstream end of the Assessment Area (AA)	3
Photo 7.	Three Springs Gulch Reconnaissance efforts using aerial photography and boat survey indicated that wetlands are not supported by Three Springs Gulch within or near the Project Boundary.	4
Photo 8.	Moccasin Creek The banks were mainly comprised of soil, stabilized by mature alder (<i>Alnus incana</i>) and red willow trees and shrubs, with occasional California sycamore (<i>Platanus racemosa</i>) and narrowleaf willow (<i>Salix exigua</i>). The canopy was well-developed, providing shade throughout the creek. Herbaceous vegetation is rich, but not overly abundant; many species occurred in small patches around the tree roots.....	4
Photo 9.	Moccasin Creek The creek is accessed frequently by fishermen, with trails throughout upland areas and into the riparian zone. The left bank just upstream of the discharge point had a short erosional area, where the dirt bank has collapsed; however the established root systems have stabilized the soil and prevented complete bank failure	5
Photo 10.	Moccasin Creek Exposed alder roots at the wetted edge, diverse aquatic vegetation, and abundant bryophytes on the banks indicated a healthy system with minimal fluctuation in flows.....	5
Photo 11.	Hatch Creek Cattle grazing was present within Hatch Creek and surrounding upland areas	6
Photo 12.	Hatch Creek Red willow, mule fat (<i>Baccharis salicifolia</i>), and spice bush were present between stretches of open, rocky banks and pools. Himalayan blackberry (<i>Rubus armeniacus</i>) was present on many of the banks under canopy of red willow or upland canyon live oaks (<i>Quercus chrysolepis</i>).....	6
Photo 13.	Big Creek The Big Creek channel had no distinct bed or banks and consisted of a shallow depression formed by hillslopes converging. The creek	

	supported primarily herbaceous species, such as broad-leaved cattail (<i>Typha latifolia</i>), tall flatsedge (<i>Cyperus eragrostis</i>), annual beard grass, dallisgrass (<i>Paspalum dilatatum</i>), spike rush (<i>Eleocharis ovata</i>), and lady's thumb (<i>Persicaria maculosa</i>).....	7
Photo 14.	Big Creek The wetland is heavily influenced by cattle, as evident by grazed herbs and hoof puncture. Vehicles cross the wetland perpendicularly with no evidence of adverse effects on the wetland.....	7
Photo 15.	Kanaka Creek Downstream of the highway, multiple vertical layers of vegetation were present in horizontally diverse patches.....	8
Photo 16.	Kanaka Creek Upper portions of the creek had reduced species richness and horizontal complexity due to the dominance of Himalayan blackberry and fig (<i>Ficus carica</i>) dominance over the mid and tall layers of vegetation.....	8
Photo 17.	Deer Creek The majority of the channel was comprised of bedrock streambed and banks and supports very limited vegetation	9
Photo 18.	Deer Creek The landscape near the channel alternates between nearly barren areas of open bedrock and lower-gradient portions that support shrubs. Bedrock pools are present throughout the channel and support macroinvertebrates, crawfish, and bullfrogs (<i>Rana catesbiana</i>)	9
Photo 19.	Drainage #7 The upland grasslands end abruptly at the edge of the drainage that has nearly vertical bedrock walls and bedrock floors.....	10
Photo 20.	Drainage #7 Limited shrubs, such as buckeye (<i>Aesculus californica</i>), red willow, and spice bush grew from within the vertical-walled drainage, with the canopy just overtopping the banks of the channel	10
Photo 21.	Drainage #8 The lower portion of the channel was comprised mainly of bedrock and boulders. Vegetation was limited and included red willows and small patches of naked sedge or stream orchid (<i>Epipactis gigantea</i>) that occurred in crevices between boulders	11
Photo 22.	Drainage #8 The upper portion of Drainage #8 had a steep gradient with the streambed and banks comprised exclusively of bedrock and boulders. A series of falls, plunge-pools, chutes, and sheets formed the channel; intermittent red willows, spice bush, and buckeyes occurred in areas where sediment was present and at the channel's edge	11
Photo 23.	Drainage #8 Gardner Falls discharges to Don Pedro reservoir over bedrock, supporting very little vegetation, such as Deptford pink (<i>Dianthus armeria</i>), with overhanging buckeye and California wild grape (<i>Vitis californica</i>). This area is very scenic, and is a popular recreation area for boaters.....	12



Photo 1. Sixbit Gulch Large bedrock and boulder outcrops occurred along the perimeter of the wetland in this moderately confined drainage.



Photo 2. Sixbit Gulch Hummocks of naked sedge (*Carex nudata*) intermixed with Sonoma hedgenettle (*Stachys stricta*), springseep monkeyflower (*Mimulus guttatus*), and an occasional red willow (*Salix laevigata*).



Photo 3. Sixbit Gulch A paved road crossed the channel near transect SG-06, which appears to be unused due to dense vegetation coverage. The road provides an opening in the dense riparian shrubs for sedge, springseep monkey flower (*Mimulus guttatus*) and Sonoma hedgenettle (*Stachys stricta*) to flourish



Photo 4. Poorman's Gulch Shallow soils overlay bedrock substrates, with hummocks of naked sedge and mixed herbs.



Photo 5. Poorman's Gulch Exposed bedrock supports perennial ryegrass (*Lolium perenne*), and annual beardgrass (*Polypogon monspeliensis*) at the perimeter.



Photo 6. Poorman's Gulch Patches of red willow and spice bush (*Calycanthus occidentalis*) alternated with naked sedge hummocks and open bedrock, which occurred more frequently around pools located at the upstream end of the Assessment Area (AA) .



Photo 7. Three Springs Gulch Reconnaissance efforts using aerial photography and boat survey indicated that wetlands are not supported by Three Springs Gulch within or near the Project Boundary.




Photo 8. Moccasin Creek The banks were mainly comprised of soil, stabilized by mature alder (*Alnus incana*) and red willow trees and shrubs, with occasional California sycamore (*Platanus racemosa*) and narrowleaf willow (*Salix exigua*). The canopy was well-developed, providing shade throughout the creek. Herbaceous vegetation is rich, but not overly abundant; many species occurred in small patches around the tree roots



Photo 9. Moccasin Creek The creek is accessed frequently by fishermen, with trails throughout upland areas and into the riparian zone. The left bank just upstream of the discharge point had a short erosional area, where the dirt bank has collapsed; however the established root systems have stabilized the soil and prevented complete bank failure



Photo 10. Moccasin Creek Exposed alder roots at the wetted edge, diverse aquatic vegetation, and abundant bryophytes on the banks indicated a healthy system with minimal fluctuation in flows.



Photo 11. Hatch Creek Cattle grazing was present within Hatch Creek and surrounding upland areas



Photo 12. Hatch Creek Red willow, mule fat (*Baccharis salicifolia*), and spice bush were present between stretches of open, rocky banks and pools. Himalayan blackberry (*Rubus armeniacus*) was present on many of the banks under canopy of red willow or upland canyon live oaks (*Quercus chrysolepis*)



Photo 13. Big Creek The Big Creek channel had no distinct bed or banks and consisted of a shallow depression formed by hillslopes converging. The creek supported primarily herbaceous species, such as broad-leaved cattail (*Typha latifolia*), tall flatsedge (*Cyperus eragrostis*), annual beard grass, dallisgrass (*Paspalum dilatatum*), spike rush (*Eleocharis ovata*), and lady's thumb (*Persicaria maculosa*).



Photo 14. Big Creek The wetland is heavily influenced by cattle, as evident by grazed herbs and hoof puncture. Vehicles cross the wetland perpendicularly with no evidence of adverse effects on the wetland.



Photo 15. Kanaka Creek Downstream of the highway, multiple vertical layers of vegetation were present in horizontally diverse patches



Photo 16. Kanaka Creek Upper portions of the creek had reduced species richness and horizontal complexity due to the dominance of Himalayan blackberry and fig (*Ficus carica*) dominance over the mid and tall layers of vegetation.



Photo 17. Deer Creek The majority of the channel was comprised of bedrock streambed and banks and supports very limited vegetation



Photo 18. Deer Creek The landscape near the channel alternates between nearly barren areas of open bedrock and lower-gradient portions that support shrubs. Bedrock pools are present throughout the channel and support macroinvertebrates, crawfish, and bullfrogs (*Rana catesbiana*)



Photo 19. **Drainage #7** The upland grasslands end abruptly at the edge of the drainage that has nearly vertical bedrock walls and bedrock floors



Photo 20. **Drainage #7** Limited shrubs, such as buckeye (*Aesculus californica*), red willow, and spice bush grew from within the vertical-walled drainage, with the canopy just overtopping the banks of the channel



Photo 21. **Drainage #8** The lower portion of the channel was comprised mainly of bedrock and boulders. Vegetation was limited and included red willows and small patches of naked sedge or stream orchid (*Epipactis gigantea*) that occurred in crevices between boulders



Photo 22. **Drainage #8** The upper portion of Drainage #8 had a steep gradient with the streambed and banks comprised exclusively of bedrock and boulders. A series of falls, plunge-pools, chutes, and sheets formed the channel; intermittent red willows, spice bush, and buckeyes occurred in areas where sediment was present and at the channel's edge




Photo 23. **Drainage #8** Gardner Falls discharges to Don Pedro reservoir over bedrock, supporting very little vegetation, such as Deptford pink (*Dianthus armeria*), with overhanging buckeye and California wild grape (*Vitis californica*). This area is very scenic, and is a popular recreation area for boaters